



41SH - POLYESTER SHRINK SLEEVE FILMS STORAGE CONDITIONS

Storage recommendations

Unprinted Film

- *Temperature should be below 98.5°F (37°C) or above 50°F (10°C)*
- *Ideal storage humidity should be between 40-70% RH without exposure to direct sunlight*
- *Allow film to acclimate to press room temperatures prior to printing*
- *Keep film clean and dry.*

Since processing variables are a major factor in product performance, this information should serve only as a guide. To the best of our knowledge, the data are correct. No warranty is made or is to be implied. The Corporation assumes no obligation or liability.

March 2017